

**PRODUCT SECURITY PATCH LIST
FOR
Automated Coagulation Analyzer
(2G984-0200EN)**

CANON INC.

Trademarks

Windows® is a registered trademark of Microsoft Corporation in the United States and other countries.

This document may also include trademarks or registered trademarks of other companies.

Note that the trademark symbol "™" and the registered trademark symbol "®" may or may not be used in this document.

IMPORTANT!

1. No part of this document may be copied or reprinted, in whole or in part, without written permission.
2. The contents of this document are subject to change without prior notice and without legal obligation.
3. The contents of this document are correct to the best of our knowledge. Please inform us of any ambiguous or erroneous descriptions, missing information, etc.

REVISION RECORD					
REV.	DATE (YYYY-MM)	REASON /AUTHOR	PAGE CHANGED	SER. No.	DOC. PRODUCT.
INI.	2026-08	Anzai	-----		BU

Security Patch Package name

SPZM10-20034_202608CL_hotfix_win10_LTSC2019_x64_enu

Applicable Products for the Security Patch

S400CF	V1.4 SP0000*
	V1.4 SP0001*
	V1.4 SP0002*
	V1.4 SP0003*

Steps to Apply the Security Patch

Please follow the instruction of applying patches defined by each of the product Security Patch Package. For details, please contact the customer service for each system.

Verified Security Patch List

KB	MSRC	explanation(en-us)	URL/File Name	url
VS2012_x64	n/a	Visual C++ Redistributable for Visual Studio 2012 Update 4	vc_redist_x64.exe	https://download.microsoft.com/download/1/6/B/16B06F60-3B20-4FF2-B699-5E9B7962F9AE/VSU_4/vcredist_x64.exe
VS2019_x64	n/a	Microsoft Visual C++ Visual Studio 2015-2019	vc_redist.x64.exe	https://download.visualstudio.microsoft.com/download/pr/9565895b-35a6-434b-a881-11a6f4beec76/EE84FED2552E018E854D4CD2496DF4DD516F30733A27901167B8A9882119E57C/VC_redist.x64.exe
KB5005112	n/a	2021-08 Servicing Stack Update for Windows 10 Version 1809 for x64-based Systems (KB5005112)	windows10.0-kb5005112-x64_81d09dc6978520e1a6d44b3b15567667f83eba2c.msu	https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/secu/2021/08/windows10.0-kb5005112-x64_81d09dc6978520e1a6d44b3b15567667f83eba2c.msu
KB5120238	n/a	2026-08 Cumulative Update for Windows 10 Version 1809 for x64-based Systems (KB5120238)	windows10.0-kb5120238-x64_9260c045d550484393347c8505b2c7252f488ed5.msu	https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/secu/2026/08/windows10.0-kb5120238-x64_9260c045d550484393347c8505b2c7252f488ed5.msu
KB5120698	n/a	2026-08 Cumulative Update for .NET Framework 3.5 and 4.7.2 for Windows 10 Version 1809 for x64 (KB5120698)	windows10.0-kb5120698-x64_1113e54f2a90f3fb05723bb07fb752c21919ecf4.msu	https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/secu/2026/07/windows10.0-kb5120698-x64_1113e54f2a90f3fb05723bb07fb752c21919ecf4.msu

KB	MSRC	explanation(en-us)	URL/File Name	url
KB890830_v5.144	n/a	Windows Malicious Software Removal Tool x64 - v5.144 (KB890830)	windows-kb890830-x64-v5.144.exe	https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/uprl/2026/08/windows-kb890830-x64-v5.144_a43bf735764ea1c5ae2a1bd15602a9a6baf378e7.exe



LEGAL MANUFACTURER

CANON INC.

30-2, SHIMOMARUKO 3-CHOME, OHTA-KU, TOKYO 146-8501, JAPAN