

**PRODUCT SECURITY PATCH LIST  
FOR  
MRI SCANNER  
(2G984-0076EN)**

**CANON MEDICAL SYSTEMS CORPORATION**

## Trademarks

Windows® is a registered trademark of Microsoft Corporation in the United States and other countries.

This document may also include trademarks or registered trademarks of other companies.

Note that the trademark symbol "™" and the registered trademark symbol "®" may or may not be used in this document.

### **IMPORTANT!**

1. No part of this document may be copied or reprinted, in whole or in part, without written permission.
2. The contents of this document are subject to change without prior notice and without legal obligation.
3. The contents of this document are correct to the best of our knowledge. Please inform us of any ambiguous or erroneous descriptions, missing information, etc.

| REVISION RECORD |                   |                       |                 |             |                  |
|-----------------|-------------------|-----------------------|-----------------|-------------|------------------|
| REV.            | DATE<br>(YYYY-MM) | REASON<br><br>/AUTHOR | PAGE<br>CHANGED | SER.<br>No. | DOC.<br>PRODUCT. |
| INI.            | 2025-07           | Abe                   | -----           |             | NASU             |

Security Patch Package name

SPZM45-20072\_202506MR\_hotfix\_win10\_LTSC2019\_x64\_enu

Applicable Products for the Security Patch

|                  |          |                             |
|------------------|----------|-----------------------------|
| Vantage Galan 3T | MRT-3020 | V7.0 SP0030* - V7.0 SP0033* |
|                  |          | V6.0 SP2010* - V6.0 SP2014* |
|                  |          | V7.0 SP0050* - V7.0 SP0063* |
| Vantage Orian    | MRT-1550 | V7.0 SP0020* - V7.0 SP0023* |
|                  |          | V6.0 SP2000* - V6.0 SP2004* |
|                  |          | V7.0 SP0040* - V7.0 SP0063* |
|                  |          | V7.0 SP5000* - V7.0 SP5010* |
| Vantage Titan 3T | MRT-3010 | V6.0 SP2030* - V6.0 SP2031* |

Steps to Apply the Security Patch

Please follow the instruction of applying patches defined by each of the product Security Patch Package. For details, please contact the customer service for each system.

Verified Security Patch List

| KB            | MSR C    | explanation(en-us)                                                                               | URL/File Name     | url                                                                                                                                                                                                                                                                                                                                                                           |
|---------------|----------|--------------------------------------------------------------------------------------------------|-------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| KB2565063_x86 | MS11-025 | Security Update for Microsoft Visual C++ 2010 Service Pack 1 Redistributable Package (KB2565063) | vc_redist_x86.exe | <a href="https://catalog.s.download.windowsupdate.com/msdownload/update/software/secur/2011/07/vcredist_x86_28c54491be70c38c97849c3d8cfbffd0d3c515cb.exe">https://catalog.s.download.windowsupdate.com/msdownload/update/software/secur/2011/07/vcredist_x86_28c54491be70c38c97849c3d8cfbffd0d3c515cb.exe</a>                                                                 |
| KB2565063_x64 | MS11-025 | Security Update for Microsoft Visual C++ 2010 Service Pack 1 Redistributable Package (KB2565063) | vc_redist_x64.exe | <a href="https://catalog.s.download.windowsupdate.com/msdownload/update/software/secur/2011/07/vcredist_x64_15d032d669078aa6f0f7fd1cbf4115a070bd034d.exe">https://catalog.s.download.windowsupdate.com/msdownload/update/software/secur/2011/07/vcredist_x64_15d032d669078aa6f0f7fd1cbf4115a070bd034d.exe</a>                                                                 |
| VS2013_x86    | n/a      | Visual C++ Redistributable Packages for Visual Studio 2013                                       | vc_redist_x86.exe | <a href="https://download.microsoft.com/download/c/c/2/cc2df5f8-4454-44b4-802d-5ea68d086676/vcredist_x86.exe">https://download.microsoft.com/download/c/c/2/cc2df5f8-4454-44b4-802d-5ea68d086676/vcredist_x86.exe</a>                                                                                                                                                         |
| VS2013_x64    | n/a      | Visual C++ Redistributable Packages for Visual Studio 2013                                       | vc_redist_x64.exe | <a href="https://download.microsoft.com/download/c/c/2/cc2df5f8-4454-44b4-802d-5ea68d086676/vcredist_x64.exe">https://download.microsoft.com/download/c/c/2/cc2df5f8-4454-44b4-802d-5ea68d086676/vcredist_x64.exe</a>                                                                                                                                                         |
| VS2019_x86    | n/a      | Microsoft Visual C++ 2015-2019 x86                                                               | vc_redist.x86.exe | <a href="https://download.visualstudio.microsoft.com/download/pr/8c211be1-c537-4402-82e7-a8fb5ee05e8a/AC96016F1511AE3EB5EC9DE04551146FE351B7F97858DCD67163912E2302F5D6/VC_redist.x86.exe">https://download.visualstudio.microsoft.com/download/pr/8c211be1-c537-4402-82e7-a8fb5ee05e8a/AC96016F1511AE3EB5EC9DE04551146FE351B7F97858DCD67163912E2302F5D6/VC_redist.x86.exe</a> |

| KB              | MSR<br>C | explanation(en-us)                                                                                                     | URL/File Name                                                                      | url                                                                                                                                                                                                                                                                                                                                                                           |
|-----------------|----------|------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| VS2019_x64      | n/a      | Microsoft Visual C++<br>2015-2019 x64                                                                                  | vc_redist.x64.exe                                                                  | <a href="https://download.visualstudio.microsoft.com/download/pr/8c211be1-c537-4402-82e7-a8fb5ee05e8a/B6C82087A2C443DB859FDBEAAE7F46244D06C3F2A7F71C35E50358066253DE52/VC_redist.x64.exe">https://download.visualstudio.microsoft.com/download/pr/8c211be1-c537-4402-82e7-a8fb5ee05e8a/B6C82087A2C443DB859FDBEAAE7F46244D06C3F2A7F71C35E50358066253DE52/VC_redist.x64.exe</a> |
| KB5005112       | n/a      | 2021-08 Servicing Stack<br>Update for Windows 10<br>Version 1809 for x64-<br>based Systems<br>(KB5005112)              | windows10.0-kb5005112-<br>x64_81d09dc6978520e1<br>a6d44b3b15567667f83eb<br>a2c.msu | <a href="https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/secu/2021/08/windows10.0-kb5005112-x64_81d09dc6978520e1a6d44b3b15567667f83eba2c.msu">https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/secu/2021/08/windows10.0-kb5005112-x64_81d09dc6978520e1a6d44b3b15567667f83eba2c.msu</a>                                     |
| KB890830_v5.134 | n/a      | Windows Malicious<br>Software Removal Tool<br>x64 - v5.134 (KB890830)                                                  | windows-kb890830-x64-<br>v5.134.exe                                                | <a href="https://catalog.s.download.windowsupdate.com/c/msdownload/update/software/uprl/2025/06/windows-kb890830-x64-v5.134_a2ddaf9c044f6e6b5bd87b0e494152498503f0e4.exe">https://catalog.s.download.windowsupdate.com/c/msdownload/update/software/uprl/2025/06/windows-kb890830-x64-v5.134_a2ddaf9c044f6e6b5bd87b0e494152498503f0e4.exe</a>                                 |
| KB5054695       | n/a      | 2025-04 Cumulative<br>Update for .NET<br>Framework 3.5 and 4.7.2<br>for Windows 10 Version<br>1809 for x64 (KB5054695) | windows10.0-kb5054695-<br>x64_afdd257a714567eef<br>1c721a9b16b04396d997<br>5a0.msu | <a href="https://catalog.s.download.windowsupdate.com/c/msdownload/update/software/updt/2025/03/windows10.0-kb5054695-x64_afdd257a714567eef1c721a9b16b04396d9975a0.msu">https://catalog.s.download.windowsupdate.com/c/msdownload/update/software/updt/2025/03/windows10.0-kb5054695-x64_afdd257a714567eef1c721a9b16b04396d9975a0.msu</a>                                     |
| KB5060531       | n/a      | 2025-06 Cumulative<br>Update for Windows 10<br>Version 1809 for x64-<br>based Systems<br>(KB5060531)                   | windows10.0-kb5060531-<br>x64_83789c3b9350e10e<br>207370622c4ef54dd685e<br>e02.msu | <a href="https://catalog.s.download.windowsupdate.com/c/msdownload/update/software/secu/2025/06/windows10.0-kb5060531-x64_83789c3b9350e10e207370622c4ef54dd685ee02.msu">https://catalog.s.download.windowsupdate.com/c/msdownload/update/software/secu/2025/06/windows10.0-kb5060531-x64_83789c3b9350e10e207370622c4ef54dd685ee02.msu</a>                                     |
| KB5019181       | n/a      | 2023-03 Update for<br>Windows 10 Version 1809<br>for x64-based Systems<br>(KB5019181)                                  | windows10.0-kb5019181-<br>x64_01173052877dc576<br>2f73069a958c108afd112<br>5be.msu | <a href="https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/updt/2023/02/windows10.0-kb5019181-x64_01173052877dc5762f73069a958c108afd1125be.msu">https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/updt/2023/02/windows10.0-kb5019181-x64_01173052877dc5762f73069a958c108afd1125be.msu</a>                                     |



LEGAL MANUFACTURER

**CANON MEDICAL SYSTEMS CORPORATION**

---

1385, SHIMOISHIGAMI, OTAWARA-SHI, TOCHIGI 324-8550, JAPAN