

**PRODUCT SECURITY PATCH LIST
FOR
X-RAY CT SCANNER
(2G984-0084EN)**

CANON MEDICAL SYSTEMS CORPORATION

Trademarks

Windows® is a registered trademark of Microsoft Corporation in the United States and other countries.

This document may also include trademarks or registered trademarks of other companies.

Note that the trademark symbol "™" and the registered trademark symbol "®" may or may not be used in this document.

IMPORTANT!

1. No part of this document may be copied or reprinted, in whole or in part, without written permission.
2. The contents of this document are subject to change without prior notice and without legal obligation.
3. The contents of this document are correct to the best of our knowledge. Please inform us of any ambiguous or erroneous descriptions, missing information, etc.

REVISION RECORD					
REV.	DATE (YYYY-MM)	REASON /AUTHOR	PAGE CHANGED	SER. No.	DOC. PRODUCT.
INI.	2025-07	Kikuchi	-----		NASU

Security Patch Package name

SPZX76-20095_202505CT_hotfix_Server2016_x64_enu

Applicable Products for the Security Patch

Aquilion Prime SP V10.2, V10.4, V10.17, Base V16.2SP0001 is not applicable	TSX-303B
Aquilion Lightning V10.2, V10.4, V10.17, Base V16.2SP0001 is not applicable	TSX-036A
Aquilion ONE V10.0, V10.4, V10.11, V10.12, V10.16, Base V16.5SP0001 is not applicable	TSX-305A/ TSX-306A
Aquilion Exceed LB V10.9, V10.18	TSX-202A
Aquilion LB V6.6, V6.7	TSX-201A

Steps to Apply the Security Patch

Please follow the instruction of applying patches defined by each of the product Security Patch Package. For details, please contact the customer service for each system.

Verified Security Patch List

KB	MSRC	explanation(en-us)	URL/File Name	url
KB2538242_x86	MS11-025	Microsoft Visual C++ 2005 Service Pack 1 Redistributable Package MFC Security Update	vc redistrib_x86.exe	https://catalog.s.download.windowsupdate.com/msdownload/update/software/secu/2011/06/vcredist_x86_b8fab0bb7f62a24ddfe77b19cd9a1451abd7b847.exe
KB2538242_x64	MS11-025	Microsoft Visual C++ 2005 Service Pack 1 Redistributable Package MFC Security Update	vc redistrib_x64.exe	https://catalog.s.download.windowsupdate.com/msdownload/update/software/secu/2011/06/vcredist_x64_ee916012783024dac67fc606457377932c826f05.exe
KB2538243_x86	MS11-025	Security Update for Microsoft Visual C++ 2008 Service Pack 1 Redistributable Package (KB2538243)	vc redistrib_x86.exe	https://catalog.s.download.windowsupdate.com/msdownload/update/software/secu/2011/05/vcredist_x86_470640aa4bb7db8e69196b5edb0010933569e98d.exe
KB2538243_x64	MS11-025	Security Update for Microsoft Visual C++ 2008 Service Pack 1 Redistributable Package (KB2538243)	vc redistrib_x64.exe	https://catalog.s.download.windowsupdate.com/msdownload/update/software/secu/2011/05/vcredist_x64_a7c83077b8a28d409e36316d2d7321fa0ccdb7e8.exe

KB	MSRC	explanation(en-us)	URL/File Name	url
KB2565063_x86	MS11-025	Microsoft Visual C++ 2010 Service Pack 1 Redistributable Package MFC Security Update	vc_redist_x86.exe	https://catalog.s.download.windowsupdate.com/msdownload/update/software/secu/2011/07/vcredist_x86_28c54491be70c38c97849c3d8cfbffd0d3c515cb.exe
KB2565063_x64	MS11-025	Microsoft Visual C++ 2010 Service Pack 1 Redistributable Package MFC Security Update	vc_redist_x64.exe	https://catalog.s.download.windowsupdate.com/msdownload/update/software/secu/2011/07/vcredist_x64_15d032d669078aa6f0f7fd1cbf4115a070bd034d.exe
VS2017_x86	n/a	Microsoft Visual C++ Visual Studio 2017	vc_redist.x86.exe	https://download.visualstudio.microsoft.com/download/pr/12319034/ccd261eb0e095411af3b306273231b68/VC_redist.x86.exe
VS2017_x64	n/a	Microsoft Visual C++ Visual Studio 2017	vc_redist.x64.exe	https://download.visualstudio.microsoft.com/download/pr/11100230/15ccb3f02745c7b206ad10373cbca89b/VC_redist.x64.exe
KB5058524	n/a	2025-05 Servicing Stack Update for Windows Server 2016 for x64-based Systems (KB5058524)	windows10.0-kb5058524-x64_d9c1dcfba3fc77d9e876d463f9df533c416ca2be.msu	https://catalog.s.download.windowsupdate.com/c/msdownload/update/software/secu/2025/05/windows10.0-kb5058524-x64_d9c1dcfba3fc77d9e876d463f9df533c416ca2be.msu
KB5058383	n/a	2025-05 Cumulative Update for Windows Server 2016 for x64-based Systems (KB5058383)	windows10.0-kb5058383-x64_f2e34deb03d8284d2bc746589ec83fd20747edd0.msu	https://catalog.s.download.windowsupdate.com/c/msdownload/update/software/secu/2025/05/windows10.0-kb5058383-x64_f2e34deb03d8284d2bc746589ec83fd20747edd0.msu
KB890830_v5.134	n/a	Windows Malicious Software Removal Tool x64 - v5.134 (KB890830)	windows-kb890830-x64-v5.134.exe	https://catalog.s.download.windowsupdate.com/c/msdownload/update/software/uprl/2025/06/windows-kb890830-x64-v5.134_a2ddaf9c044f6b6b5bd87b0e494152498503f0e4.exe
KB5019182	n/a	2023-04 Update for Windows Server 2016 for x64-based Systems (KB5019182)	windows10.0-kb5019182-x64_9dda0f01f337746913602d2c7269f5aa9cea9235.msu	https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/updt/2023/04/windows10.0-kb5019182-x64_9dda0f01f337746913602d2c7269f5aa9cea9235.msu



LEGAL MANUFACTURER

CANON MEDICAL SYSTEMS CORPORATION

1385, SHIMOISHIGAMI, OTAWARA-SHI, TOCHIGI 324-8550, JAPAN