

**PRODUCT SECURITY PATCH LIST
FOR
MRI SCANNER
(2G984-0115EN)**

CANON MEDICAL SYSTEMS CORPORATION

Trademarks

Windows® is a registered trademark of Microsoft Corporation in the United States and other countries.

This document may also include trademarks or registered trademarks of other companies.

Note that the trademark symbol "™" and the registered trademark symbol "®" may or may not be used in this document.

IMPORTANT!

1. No part of this document may be copied or reprinted, in whole or in part, without written permission.
2. The contents of this document are subject to change without prior notice and without legal obligation.
3. The contents of this document are correct to the best of our knowledge. Please inform us of any ambiguous or erroneous descriptions, missing information, etc.

REVISION RECORD					
REV.	DATE (YYYY-MM)	REASON /AUTHOR	PAGE CHANGED	SER. No.	DOC. PRODUCT.
INI.	2025-11	Murakami	-----		NASU

Security Patch Package name

SPZM45-20079_202511MR_hotfix_win10_LTSC2019_x64_enu

Applicable Products for the Security Patch

Vantage Galan 3T	MRT-3020	V7.0 SP0030* - V7.0 SP0033*
		V6.0 SP2010* - V6.0 SP2014*
		V7.0 SP0050* - V7.0 SP0063*
Vantage Orian	MRT-1550	V7.0 SP0020* - V7.0 SP0023*
		V6.0 SP2000* - V6.0 SP2004*
		V7.0 SP0040* - V7.0 SP0063*
		V7.0 SP5000* - V7.0 SP5010*
Vantage Titan 3T	MRT-3010	V6.0 SP2030* - V6.0 SP2031*

Steps to Apply the Security Patch

Please follow the instruction of applying patches defined by each of the product Security Patch Package. For details, please contact the customer service for each system.

Verified Security Patch List

KB	MSR C	explanation(en-us)	URL/File Name	url
KB2565063_x86	MS11-025	Security Update for Microsoft Visual C++ 2010 Service Pack 1 Redistributable Package (KB2565063)	vc_redist_x86.exe	https://catalog.s.download.windowsupdate.com/msdownload/update/software/secur/2011/07/vcredist_x86_28c54491be70c38c97849c3d8cfbffd0d3c515cb.exe
KB2565063_x64	MS11-025	Security Update for Microsoft Visual C++ 2010 Service Pack 1 Redistributable Package (KB2565063)	vc_redist_x64.exe	https://catalog.s.download.windowsupdate.com/msdownload/update/software/secur/2011/07/vcredist_x64_15d032d669078aa6f0f7fd1cbf4115a070bd034d.exe
VS2013_x86	n/a	Visual C++ Redistributable Packages for Visual Studio 2013	vc_redist_x86.exe	https://download.microsoft.com/download/c/c/2/cc2df5f8-4454-44b4-802d-5ea68d086676/vcredist_x86.exe
VS2013_x64	n/a	Visual C++ Redistributable Packages for Visual Studio 2013	vc_redist_x64.exe	https://download.microsoft.com/download/c/c/2/cc2df5f8-4454-44b4-802d-5ea68d086676/vcredist_x64.exe
VS2019_x86	n/a	Microsoft Visual C++ 2015-2019 x86	vc_redist.x86.exe	https://download.visualstudio.microsoft.com/download/pr/8c211be1-c537-4402-82e7-a8fb5ee05e8a/AC96016F1511AE3EB5EC9DE04551146FE351B7F97858DCD67163912E2302F5D6/VC_redist.x86.exe

KB	MSR C	explanation(en-us)	URL/File Name	url
VS2019_x64	n/a	Microsoft Visual C++ 2015-2019 x64	vc_redist.x64.exe	https://download.visualstudio.microsoft.com/download/pr/8c211be1-c537-4402-82e7-a8fb5ee05e8a/B6C82087A2C443DB859FDBEAAE7F46244D06C3F2A7F71C35E50358066253DE52/VC_redist.x64.exe
KB5005112	n/a	2021-08 Servicing Stack Update for Windows 10 Version 1809 for x64- based Systems (KB5005112)	windows10.0-kb5005112- x64_81d09dc6978520e1 a6d44b3b15567667f83eb a2c.msu	https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/secu/2021/08/windows10.0-kb5005112-x64_81d09dc6978520e1a6d44b3b15567667f83eba2c.msu
KB890830_v5.137	n/a	Windows Malicious Software Removal Tool x64 - v5.137 (KB890830)	windows-kb890830-x64- v5.137.exe	https://catalog.s.download.windowsupdate.com/c/msdownload/update/software/uprl/2025/11/windows-kb890830-x64-v5.137_d26124d4bdd1a7259db3b081f198db147c7dec0b.exe
KB5066143	n/a	2025-10 Cumulative Update for .NET Framework 3.5 and 4.7.2 for Windows 10 Version 1809 for x64 (KB5066143)	windows10.0-kb5066143- x64_461230ac1884e969 1f54936b91ff04e46b80c2 bc.msu	https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/secu/2025/09/windows10.0-kb5066143-x64_461230ac1884e9691f54936b91ff04e46b80c2bc.msu
KB5068791	n/a	2025-11 Cumulative Update for Windows 10 Version 1809 for x64- based Systems (KB5068791)	windows10.0-kb5068791- x64_a8b1b1b6c7b6b673 c5a5f32772749eb2bb80c 88b.msu	https://catalog.s.download.windowsupdate.com/c/msdownload/update/software/secu/2025/11/windows10.0-kb5068791-x64_a8b1b1b6c7b6b673c5a5f32772749eb2bb80c88b.msu
KB5019181	n/a	2023-03 Update for Windows 10 Version 1809 for x64-based Systems (KB5019181)	windows10.0-kb5019181- x64_01173052877dc576 2f73069a958c108afd112 5be.msu	https://catalog.s.download.windowsupdate.com/d/msdownload/update/software/updt/2023/02/windows10.0-kb5019181-x64_01173052877dc5762f73069a958c108afd1125be.msu



LEGAL MANUFACTURER

CANON MEDICAL SYSTEMS CORPORATION

1385, SHIMOISHIGAMI, OTAWARA-SHI, TOCHIGI 324-8550, JAPAN